



Instructions

Pipe and Drape

1-10 x 10 Section of Pipe and drape

Includes:

- 1-6ft-10ft expandable crossbar
- 2-uprights
- 2-base plates
- 4-panels of drape

Instructions for Set-up

1. Adjust expandable crossbar to the desired length and lock into place.
2. Lay the base plates on the floor on each side of the adjustable crossbar and insert uprights onto base plates.
***Note:** Ensure that the slots on the uprights are at the top and not at the bottom, as this is where the crossbar will hook.
3. Thread drape panels (seam side back) onto crossbar and hook crossbar into uprights.

If you have questions with the operation of this equipment, we can be reached at 317-251-7368 during our standard business hours.



Trade Show Booth

1- 10' x 10' Section + 2- 3' tall side sections

